

1. AIRPLANE 3A2 FLIGHTS AS FOLLOWS:

ing 40 - 2 july - 4820 - autopilot test at heavy weight.

NR 41 6 JULY - 2849 - ENGINE TEST.

AUTOPIEDT TESTS HAVE RESULTED IN CHANGES IN THE BASIC SETTINGS.

MAJOR IMPROVEMENTS IN AUTOPILOT OPERATION HAVE BEEN ACCOMPLISHED.

TESTS ARI CONTINUING. THE ENGINE THAT HAS HAD A FLAMEOUT

HISTORY VAS INSTALLED AND TESTS MADE ON FLIGHT 41. A FLAMEOUT

WAS ENCOUNTERED AT 56,000 FEET. DATA ARE BEING ANALYZED.

AIRPLANE 355 FLIGHT AS FOLLOWS: 25X1A

NR 16 - 2 JULY - 1:52 - ANSITION.

NR 17 - 2 JULY - 5:12 - A GULY - 6:15 - A GULY - 6:32 - AULY - 6:32 - AULY - 6:33 - AULY - 6:33

3-

SECRET

25X1A

353% (IN %2696)

PAGE 2

NR 21 - 6 JULY - 6:40 - B CAMERA.

EFGINE OPERATION HAS BEEN EVIDENCED BY BANGING DURING CLIMB
BETWEEN 40,000 AND 60,000 FEET. THIS CAN BE AVOIDED BY CLIMBING
AT REDUCED POWER. OTHERVISE ENGINE OPERATION HAS BEEN SATISFACTORY.

INPROVEMENTS HAVE BEEN MADE IN THE AUTOPILOT PARTLY DUE TO
RESULTS OF TESTS IN 342 AND OPERATION IS NOW CONSIDERED SATISFACTORY.

SOME TROUBLE HAS BEEN EXPERIENCED WITH PRESSURIZATION OF THE
EQUIPMENT BAY AT HIGH ALTITUDE. THIS PROBLEM IS BEING WORKED

OUT. HIGH OIL TEMP CONTINUES TO LIMIT HIGH ALTITUDE PERFORMANCE.

A MODIFIED HEAT EXCHANGER HAS BEEN INSTALLED ON NR 342 AND

WILL BE TESTED ON NEXT FLIGHT.

- 3. AIRPLANE 351 IS BEING ASSEMBLED AND CHECKED OUT. INITIAL FLIGHT EXPECTED LATE THIS WEEK.
  - 4. TOTAL PLIGHT TIME ON J-75 IS 175 HOURS.

END OF MESSAGE

SECRET